



September 1, 2018

Re: Compliance with U.S. Green Building Council's LEED Program
(Leadership in Energy and Environmental Design)
Compliance with South Coast Air Quality Management District (SCAQMD)
Rule 1168, Oct. 6, 2017

To Whom it May Concern:

The following Metzger/McGuire joint fillers and repair products are all composed of 100% solids and contain no (0%) VOC's (volatile organic compounds):

Joint Fillers:

MM-80 Heavy Duty, Semi-Rigid Epoxy Joint Filler
MM-80P Heavy Duty, Semi-Rigid Epoxy Joint Filler
Edge-Pro 80 Moisture Tolerant Semi-Rigid Polyurea Joint Filler (LEED v4 Tested)
Spal-Pro RS-88 Heavy Duty, Semi-Rigid Polyurea Joint Filler (LEED v4 Tested)
Spal-Pro RSF Heavy Duty, Semi-Rigid Polyurea Joint Filler
Spal-Pro RS-65 Semi-Rigid Polyurea Joint Sealant
Spal-Pro 2000 Heavy Duty Polyurea Repair Polymer

Repair Products:

Armor-Hard Extreme Rapid Set Epoxy Mortar System
Armor-Hard Kit – Epoxy Mortar System
Armor-Hard Early Set Structural Epoxy Liquid
Rapid Refloor Fast Set, Low Viscosity Structural Repair Polymer
Rapid Refloor Pit Grout, Low Viscosity Rapid Set Surface Restoration Polymer
Spal-Pro Stabilizer Rapid Set, Semi-Rigid Injection Polyurea

None of the above referenced products exceed the VOC safety guidelines established by the U.S. EPA and all are fully compliant with the criteria set forth to qualify for the ***IEQ4.1 Low-emitting adhesives, sealants*** credit by the U.S. Green Building Council's LEED (Leadership in Energy and Environmental Design) program. These products also do not exceed limits required for compliance with the South Coast Air Quality Management District (SCAQMD) Rule 1168, Oct. 6, 2017

Please contact us should you have further questions regarding this issue.

Cordially,

Scott Metzger

800-223-MM80

www.metzgermcguire.com

P.O. Box 2217 Concord, NH 03302